

GOVERNMENT OF ANDHRA PRADESH  
ROADS & BUILDINGS DEPARTMENT

From,  
Sri. V. Kesava Rao, B.E.,  
Executive Engineer( R & B),  
Visakhapatnam.

To,  
The Sri Chaitanya Vidya Nikethan,  
Marikavalasa, Madhurawada,  
Visakhapatnam.

Respected Sir,

Sub:- (R & B) Division, Visakhapatnam, Sri Chaitanya Vidya Nikethan, Marikavalasa, Madhurawada, Visakhapatnam – Structural Soundness Certificate -Issued – Req- Reg.


\* \* \*

With the above cited subject, It is informed that the Sri Chaitanya Vidya Nikethan, Marikavalasa, Madhurawada, Visakhapatnam was inspected by me on 26-11-2020 and the above Building is Structurally Sound. As observed the building is in good condition.

It is Certified that the Sri Chaitanya Vidya Nikethan, , Marikavalasa, Madhurawada, Visakhapatnam is structurally sound.



Yours faithfully,

  
Executive Engineer ( R & B )  
Visakhapatnam  
Visakhapatnam-18